

September 29, 2011

Husqvarna Professional Products Recalls RedMax Brushcutter Due to Fire Hazard

Subject: Recalls RedMax Brushcutter Due to Fire Hazard

Name of Product: RedMax brushcutter / trimmer

Units: About 10,500

Manufacturer: Husqvarna Zenoah Co. Ltd. is an affiliate of Husqvarna Professional Products Inc., Charlotte, N.C.

Hazard: Some fuel tanks allow leakage at the fuel cap, posing a fire hazard to consumers.

Incidents/Injuries: No reports of fire, personal injury or property damage.

Description: The recalled brushcutter / trimmer is a RedMax model TR2350S.

Recalled brushcutters have shaft serial numbers ranging from 10215377 to 10625892, and engine serial numbers ranging from 10115390 to 10425910. The product is powered by a 2-cycle gasoline engine and cuts grass or weeds through the use of a spinning black trimmer head containing a spool of filament line. Model number and shaft serial number are located on a label on the shaft halfway between the trimmer head and the engine. The engine serial number is located on the bottom of engine between the two screws that secure fuel tank to the engine. See illustration below.

Sold at: Authorized RedMax dealers and distributors throughout the U.S. and Canada for about \$260.00.

Remedy: Consumers should immediately stop using the product and return it to their local RedMax dealer for repair.

Consumer Contact: For additional information, please contact Husqvarna toll-free between 8 a.m. and 6 p.m. ET Monday through Friday at (877) 257-6921 or e-mail recalls@husqvarna.com

To see this recall on CPSC's web site, including pictures of the recalled product, please go to: <http://www.cpsc.gov/cpscpub/prereel/prhtml11/11341.html>